



3RG - 30710 - Kit reparación cables bujía de precalentamiento

Kit reparación cables bujía de precalentamiento

Referencias O.E.M: 028971766;028971220A;038971782;

Aplicación: AUDI: A3 (8L1) ; SEAT: ALHAMBRA (7V8, 7V9) , ALHAMBRA VAN (7V8, 7V9) , AROSA (6H1) , CORDOBA (6K1, 6K2) , CORDOBA Vario (6K5) , IBIZA II (6K1) , INCA (6K9) , LEON (1M1) , TOLEDO I (1L2) , TOLEDO II (1M2) ; SKODA: OCTAVIA I (1U2) , OCTAVIA I Combi (1U5) , OCTAVIA I Furgón/ranchera familiar (1U5) ; VW: BORA I (1J2) , BORA Variant (1J6) , CADDY II Furgoneta/monovolumen (9K9A) , CADDY II Monospace (9K9B) , GOLF III (1H1) , GOLF III Cabriolet (1E7) , GOLF III Van (1H1) , GOLF III Variant (1H5) , GOLF IV (1J1) , GOLF IV Cabriolet (1E7) , GOLF IV Van (1J1) , GOLF IV Variant (1J5) , GOLF Van III Variant (1H5) , GOLF VAN IV Variant (1J5) , LUPO I (6X1, 6E1) , NEW BEETLE (9C1, 1C1) , PASSAT B3/B4 (3A2, 35I) , PASSAT B3/B4 Variant (3A5, 35I) , PASSAT B5 (3B2) , PASSAT B5 Variant (3B5) , POLO (6N2) , POLO III (6N1) , POLO III CLASSIC (6V2) | FLIGHT , POLO Variant (6V5) , SHARAN (7M8, 7M9, 7M6) , SHARAN VAN (7M_) , VENTO (1H2)