



3RG - 36501 - Kit reparacion colector admision

Kit reparacion colector admision

Referencias O.E.M: 6420903837;A6420902837;68023871AA;

Aplicación: MERCEDES-BENZ: SPRINTER 2-t Autobús (B901, B902) , SPRINTER 2-t Caja/Chasis (B901, B902) , SPRINTER 2-t Furgón (B901, B902) , SPRINTER 3-t Autobús (B903) , SPRINTER 3-t Autobús (B906) , SPRINTER 3-t Caja/Chasis (B903) , SPRINTER 3-t Tourer Bus (B907) , SPRINTER 3,5-t Autobús (B906) , SPRINTER 3,5-t Caja/Chasis (B906) , SPRINTER 3,5-t Caja/Chasis (B907, B910) , SPRINTER 3,5-t Furgón (B906) , SPRINTER 3,5-t Furgón (B907, B910) , SPRINTER 3,5-t Tourer Bus (B907) , SPRINTER 5-t Autobús (B906) , SPRINTER 5-t Caja/Chasis (B906) , SPRINTER 5-t Caja/Chasis (B907)