



3RG - 74601 - Kit reparación bomba vacío (5pcs)

Kit reparación bomba vacío (5pcs)

Referencias O.E.M: 8200521381;146505272R;8201005306;1465000Q1G;

Aplicación: RENAULT: CAPTUR I (J5_, H5_), CLIO II (BB_, CB_), CLIO III (BR0/1, CR0/1), CLIO IV (BH_), CLIO V (B7_), DOKKER, DUSTER (HM_), DUSTER (HS_), FLUENCE (L3_), KADJAR (HA_, HL_), KANGOO (KC0/1_), KANGOO / GRAND KANGOO II (KW0/1_), LAGUNA III (BT0/1), LATITUDE (L70_), LODGY (JS_), MASTER II Autobús (JD), MASTER II Caja/Chasis (ED/HD/UD), MASTER II Furgón (FD), MEGANE II (BM0/1_, CM0/1_), MEGANE III Combi Van (KZ0/1), MEGANE IV Fastback (B9A/M/N_), MEGANE IV Sedán, MODUS / GRAND MODUS (F/JP0_), SANDERO/STEPWAY II (B8_), SCALA (LJM_), SCÉNIC II (JM0/1_), SCÉNIC III (JZ0/1_), SCÉNIC IV (J9_), TALISMAN (LP_), THALIA I (LB_) | CLIO SYMBOL, TWINGO II (CN0_)