



3RG - 82691 - Kit reparación cables motor de ventilador interior

Kit reparación cables motor de ventilador interior

Referencias O.E.M: 7701048390;6441L2;7701207718;27761AX010;

Aplicación: CITROËN: C2 (JM_) , C2 ENTERPRISE (JG_) , C3 I (FC_, FN_) , C3 Pluriel (HB_) , C5 Furgón/ranchera familiar (DE_, RE_) , C5 I (DC_) , C5 I Break (DE_) ; NISSAN: NOTE (E11, NE11) ; PEUGEOT: 1007 (KM_) , 207 (WA_, WC_) | 207/207+ , 207 CC (WD_) , 207 Furgoneta/hatchback (WA_, WC_) , 207 SW (WK_) , 406 (8B) , 406 Break (8E/F) , 406 Coupé (8C) , 607 (9D, 9U) ; RENAULT: CLIO II (BB_, CB_) , CLIO III (BR0/1, CR0/1) , CLIO III Furgoneta/hatchback (SB_, SR_) , CLIO III Grandtour (KR0/1_) , GRAND SCÉNIC II (JM0/1_) , MEGANE II (BM0/1_, CM0/1_) , MEGANE II Coupé-Cabriolet (EM0/1_) , MEGANE II Furgón/ranchera familiar (KM_) , MEGANE II Hatchback Van (KM0/2_) , MEGANE II Ranchera familiar (KM0/1_) , MEGANE II Sedán (LM0/1_) , MEGANE Scenic (JA0/1_) , MEGANE Scenic VAN (JA0/1_) , MODUS / GRAND MODUS (F/JP0_) , SCÉNIC I Monospace (JA0/1_, FA0_) , SCÉNIC I VAN (FA0_, JA0/1_) , SCÉNIC II (JM0/1_) , TWINGO II (CN0_)