



3RG - 30603 - Kit reparación cables sensor arbol levas

Kit reparación cables sensor arbol levas

Referencias O.E.M: 8200673203;8200643171, 8200673202;7700101969;8200396919,
8200436025;6001543612, 6001548175;

Aplicación: RENAULT: CLIO I (B/C57_, 5/357_) , CLIO II (BB_, CB_) , CLIO II Furgoneta/hatchback (SB0/1/2_) , CLIO III (BR0/1, CR0/1) , KANGOO (KC0/1_) , KANGOO Express (FC0/1_) , MEGANE I (BA0/1_) , MEGANE I Cabriolet (EA0/1_) , MEGANE I Classic (LA0/1_) , MEGANE I Coach (DA0/1_) , MEGANE I Grandtour (KA0/1_) , MEGANE Scenic (JA0/1_) , MODUS / GRAND MODUS (F/JP0_) , TWINGO I (C06_) , TWINGO II (CN0_)