



3RG - 30605 - Kit reparación cables sensor arbol levas

Kit reparación cables sensor arbol levas

Referencias O.E.M: 8200300322;

Aplicación: RENAULT: CLIO I (B/C57_, 5/357_) , CLIO II (BB_, CB_) , CLIO II Furgoneta/hatchback (SB0/1/2_) , CLIO III (BR0/1, CR0/1) , CLIO III Furgoneta/hatchback (SB_, SR_) , CLIO III Grandtour (KR0/1_) , ESPACE III (JE0_) , ESPACE IV (JK0/1_) , KANGOO (KC0/1_) , KANGOO / GRAND KANGOO II (KW0/1_) , KANGOO BE BOP (KW0/1_) , KANGOO Express (FC0/1_) , KANGOO Express (FW0/1_) , LAGUNA II (BG0/1_) , LAGUNA II Grandtour (KG0/1_) , LAGUNA III (BT0/1) , LAGUNA III Grandtour (KT0/1) , LOGAN I Ranchera familiar (KS_) | TONDAR 90 , MASTER II Autobús (JD) , MASTER II Caja/Chasis (ED/HD/UD) , MASTER II Furgón (FD) , MEGANE I (BA0/1_) , MEGANE I Cabriolet (EA0/1_) , MEGANE I Classic (LA0/1_) , MEGANE I Coach (DA0/1_) , MEGANE I Grandtour (KA0/1_) , MEGANE II (BM0/1_, CM0/1_) , MEGANE II Coupé-Cabriolet (EM0/1_) , MEGANE II Ranchera familiar (KM0/1_) , MEGANE II Sedán (LM0/1_) , MEGANE Scenic (JA0/1_) , MODUS / GRAND MODUS (F/JPO_) , SAFRANE (A3_, L7_) , SCÉNIC II (JM0/1_) , SCÉNIC III (JZ0/1_) , SCÉNIC IV (J9_) , THALIA I (LB_) | CLIO SYMBOL , THALIA II (LU_) | SYMBOL , TRAFIC II Autobús (JL) , TRAFIC II Caja/Chasis (EL) , TRAFIC II Furgón (FL) , TWINGO I (C06_) , TWINGO II (CN0_) , VEL SATIS (BJ0_) , WIND (E4M_)