



## 3RG - 74201 - Kit reparación bomba vacío (10pcs)

Kit reparación bomba vacío (10pcs)

Referencias O.E.M: 11667806000, 3M5Q2A451AB;456570 , 3M5Q2A451AC, 3M5Q2A451AD,;9660058480, 3M5Q2A451AE, 3M5Q2A451AA,;1486107, 1229772, 1313101, 1355026, 1487860;Y60118G00A, Y60118G00C, 31259227,30711065;

Aplicación: CITROËN: BERLINGO Furgoneta/monovolumen (B9) , BERLINGO MULTISPACE (B9) , C2 (JM\_) , C3 I (FC\_, FN\_) , C3 II (SC\_) , C3 PICASSO (SH\_) , C4 Coupé (LA\_) , C4 GRAND PICASSO I (UA\_) , C4 I Sedán , C4 PICASSO I Monospace (UD\_) , C5 II (RC\_) , C5 II Break (RE\_) , C5 III (RD\_) , C5 III Break (RW\_) , JUMPY (VF7) | DISPATCH , JUMPY Furgón | DISPATCH , XSARA PICASSO (N68) ; FIAT: SCUDO Autobús (270\_, 272\_) , SCUDO Caja/Chasis (270\_, 272\_) , SCUDO Furgón (270\_, 272\_) ; FORD: C-MAX (DM2) , FIESTA V (JH\_, JD\_) , FIESTA VI (CB1, CCN) , FOCUS C-MAX (DM2) , FOCUS II (DA\_, HCP, DP) , FOCUS II Sedán (DB\_, FCH, DH) , FOCUS II Turnier (DA\_, FFS, DS) , FUSION (JU\_) ; MAZDA: 2 (DE\_, DH\_) , 3 (BK) , 3 (BL) , 3 Sedán (BK) , 3 Sedán (BL) ; MINI: MINI (R56) , MINI CLUBMAN (R55) ; PEUGEOT: 1007 (KM\_) , 206 CC (2D) , 206 Fastback (2A/C) , 206 SW (2E/K) , 207 (WA\_, WC\_) | 207/207+ , 207 CC (WD\_) , 207 SW (WK\_) , 3008 Monospace (0U\_) , 307 (3A/C) , 307 Break (3E) , 307 SW (3H) , 308 I (4A\_, 4C\_) , 308 SW I (4E\_, 4H\_) , 407 (6D\_) , 407 SW (6E\_) , 5008 (0U\_, 0E\_) , EXPERT Caja/Chasis , EXPERT Furgón (VF3A\_, VF3U\_, VF3X\_) , EXPERT TEPEE (VF3X\_) , PARTNER Furgoneta/monovolumen , PARTNER TEPEE ; VOLVO: C30 (533) , S40 II (544) , V50 (545) , V70 III (135)