



Ngk - 1044 - SUSTITUIDA POR 5098 (EXTINGUIDA)

Bujia automovil niquel

Bujia automovil niquel