



Ngk - 92739 - SUSTITUIDA POR 94375 (EXTINGUIDA)

Sonda lambda automovil

Sonda lambda automovil