



3RG - 80005 - Reparación bomba vacío

Reparación bomba vacío

Referencias O.E.M: A0015860743;

Aplicación: CITROËN: AX (ZA-_) , BX (XB-_) , VISA , XANTIA (X1_ , X2_) , XSARA (N1) ; FIAT: 131 (131_) , 132 (132_) ; MERCEDES-BENZ: /8 (W114) , /8 (W115) , /8 Coupé (W114) , 123 Sedán (W123) , 123 T-Model (S123) , CLASE S (W116) ; PEUGEOT: 106 I (1A, 1C) , 205 I (741A/C) , 309 I (10C, 10A) , 405 I (15B) , 504 , 504 (A_ , M_) , 505 (551A) , 605 (6B) ; RENAULT: 18 (134_) , 18 Furgón/ranchera familiar , 18 Variable (135_) , 19 I (B/C53_) , 20 (127_) , 21 (B48_) , 25 (B29_) , 30 (127_) , FUEGO (136_) ; SEAT: 131 (131A) , 132 (132A) ; TALBOT: HORIZON