



3RG - 81657 - Varilla aceite

Varilla aceite

Referencias O.E.M: 8200449528;

Aplicación: NISSAN: MICRA II (K11) , MICRA III (K12) ; RENAULT: CLIO II (BB_, CB_) , CLIO III (BR0/1, CR0/1) , FLUENCE (L3_) , KANGOO (KC0/1_) , KANGOO / GRAND KANGOO II (KW0/1_) , KANGOO Express (FC0/1_) , KANGOO Express (FW0/1_) , LAGUNA I (B56_, 556_) , LAGUNA II (BG0/1_) , LAGUNA II Grandtour (KG0/1_) , LAGUNA III (BT0/1) , LAGUNA III Grandtour (KT0/1) , MEGANE CC (EZ0/1_) , MEGANE I (BA0/1_) , MEGANE I Cabriolet (EA0/1_) , MEGANE I Classic (LA0/1_) , MEGANE I Coach (DA0/1_) , MEGANE I Grandtour (KA0/1_) , MEGANE II (BM0/1_, CM0/1_) , MEGANE II Coupé-Cabriolet (EM0/1_) , MEGANE II Ranchera familiar (KM0/1_) , MEGANE II Sedán (LM0/1_) , MEGANE III Coupé (DZ0/1_) , MEGANE III Fastback (BZ0/1_, B3_) , MEGANE III Grandtour (KZ0/1) , SCÉNIC I Monospace (JA0/1_, FA0_) , SCÉNIC II (JM0/1_) , SCÉNIC III (JZ0/1_)