



3RG - 30608 - Kit reparación cables sensor posición cigüeñal

Kit reparación cables sensor posición cigüeñal

Referencias O.E.M: 237313810R;4407993, 3322080K00000;A4159058000, A6079050300;2373100Q1L, 2375000Q0L, 237315X20A, 23731BC42B;95517836, 95530087, 8200885209;

Aplicación: DACIA: DOKKER Express Furgoneta/monovolumen , DOKKER Monospace (KE_) , DUSTER (HM_) , DUSTER (HS_) , DUSTER Furgoneta/SUV , LODGY (JS_) , LOGAN (LS_) , LOGAN EXPRESS (FS_) , LOGAN II , LOGAN MCV (KS_) , LOGAN MCV II , LOGAN Pick-up (US_) , SANDERO , SANDERO II ; INFINITI: EX , FX , M (Y51) , Q30 , Q70 (Y51) , QX50 I , QX70 ; MERCEDES-BENZ: CITAN Furgoneta/monovolumen (W415) , CITAN Mixto (Double Cabin) (W415) , CITAN Monospace (W415) , MARCO POLO Camper (W447) , VITO Furgón (W447) , VITO Mixto (Double Cabin) (W447) , VITO Tourer (W447) ; NISSAN: CUBE (Z12) , JUKE (F15) , JUKE Van (F15) , MICRA III (K12) , MICRA V (K14) , NOTE (E11, NE11) , NOTE (E12) , NP300 NAVARA (D40) , NP300 NAVARA Caja/Chasis (D40) , NV200 / EVALIA Autobús , NV200 Furgón , NV300 Caja/Chasis (X82) , NV300 Furgón (X82) , NV300 Kombi (X82) , PATHFINDER III (R51) , PATHFINDER III VAN (R51_) , PULSAR Fastback (C13) | TIIDA , QASHQAI / QASHQAI +2 I (J10, NJ10, JJ10E) , QASHQAI / QASHQAI +2 I VAN (J10, JJ10E) , QASHQAI II SUV (J11, J11_) , TIIDA Fastback (C11) , TIIDA Sedán (SC11) , X-TRAIL III (T32_, T32R, T32RR) ; OPEL: VIVARO B Autobús (X82) , VIVARO B Caja/Chasis (X82) , VIVARO B Furgón (X82) ; RENAULT: CAPTUR I (J5_, H5_) , CLIO II (BB_, CB_) , CLIO II Furgoneta/hatchback (SB0/1/2_) , CLIO III (BR0/1, CR0/1) , CLIO III Furgoneta/hatchback (SB_, SR_) , CLIO III Grandtour (KR0/1_) , CLIO IV (BH_) , CLIO IV Furgón/ranchera familiar (KH_) , CLIO IV Furgoneta/hatchback (BH_) , CLIO IV Grandtour (KH_) , DOKKER , DUSTER (HM_) , ESPACE V (JR_) , FLUENCE (L3_) , GRAND SCÉNIC II (JM0/1_) , GRAND SCÉNIC III (JZ0/1_) , GRAND SCÉNIC IV (R9_) , KADJAR (HA_, HL_) , KANGOO (KC0/1_) , KANGOO / GRAND KANGOO II (KW0/1_) , KANGOO BE BOP (KW0/1_) , KANGOO Express (FC0/1_) , KANGOO Express (FW0/1_) , KOLEOS II (HC_) , LAGUNA Coupé (DT0/1) , LAGUNA III (BT0/1) , LAGUNA III Grandtour (KT0/1) , LATITUDE (L70_) , LOGAN I (LS_) | TONDAR 90 , LOGAN I Ranchera familiar (KS_) | TONDAR 90 , MEGANE CC (EZ0/1_) , MEGANE II (BM0/1_, CM0/1_) , MEGANE II Coupé-Cabriolet (EM0/1_) , MEGANE II Furgón/ranchera familiar (KM_) , MEGANE II Hatchback Van (KM0/2_) , MEGANE II Ranchera familiar (KM0/1_) , MEGANE II Sedán (LM0/1_) , MEGANE III Combi Van (KZ0/1) , MEGANE III Coupé (DZ0/1_) , MEGANE III Fastback (BZ0/1_, B3_) , MEGANE III Grandtour (KZ0/1) , MEGANE III Hatchback Van (BZ_) , MEGANE IV Fastback (B9A/M/N_) , MEGANE IV Grandtour (K9A/M/N_) , MEGANE IV Sedán , MODUS / GRAND MODUS (F/JPO_) , SANDERO/STEPWAY II (B8_) , SCÉNIC II (JM0/1_) , SCÉNIC III (JZ0/1_) , SCÉNIC III VAN (JZ0/1_) , SCÉNIC IV (J9_) , TALISMAN (LP_) , TALISMAN Grandtour (KP_) , THALIA I (LB_) | CLIO SYMBOL , THALIA II (LU_) | SYMBOL , TRAFIC III Autobús (JG_) , TRAFIC III Caja/Chasis (EG_) , TRAFIC III Furgón (FG_) , TWINGO II (CN0_) ; SUZUKI: GRAND VITARA II (JT, TE, TD)